

Eklind Tool Company - Made in USA - 11040 King Street - Franklin Park, Illinois 60136-1412 Joseph F. Dwyer, Executive Vice President - 847,288.8600 (Voice) - 847,288.8610 (Fax) - Joe@ektindtool.net (e-mail)

HIPOPO INC

7/30/2007

Hippo, Inc. St. Royal Club Tanimachi 201 4-6, Tanimachi 3-Chome Chuo-Ku, Osaka 540-0012, Japan

Product Content Statement / Absence Declaration:

Reference: RoHS - Directive 2002/95/EC:

European Union (EU) - Directive Restriction of Use of Hazardous Substances - which requires the elimination of mercury, cadmium, lead, hexavalent chromium, PBB, and PBDE flame retardants:

The raw materials used in the manufacturing of Eklind products have been no intentional additions of heavy metals or brominated-flame-retardants.

After reviewing engineering bills of material, supplier furnished MSDS statements and consulting with suppliers, Eklind Tool Company has concluded that the following (6) items are not contained in our products or packaging.

Lead - (Pb) Mercury - (Hg) Cadmium - (Cd) Hexavalent Chromium (Cr, VI) Polybrominated biphenyls (PBBs) Polybrominated diphenyl ethers (PBDEs)

Certified By: Joseph Dwyer Joseph Dwyer, Executive VP / Manufacturing