



**Eklind Tool Company** - Made in USA - 11040 King Street - Franklin Park, Illinois 60136-1412  
 Joseph F. Dwyer, Executive Vice President - 847.288.8600 (Voice) - 847.288.8610 (Fax) - Joe@ekfindtool.net (e-mail)

7/30/2007

Hippo, Inc.  
 St. Royal Club Tanimachi 201  
 4-6, Tanimachi 3-Chome  
 Chuo-Ku, Osaka 540-0012, Japan

**Product Content Statement / Absence Declaration:**

Reference: RoHS – Directive 2002/95/EC:  
 European Union (EU) - Directive Restriction of Use of Hazardous Substances - which requires the elimination of mercury, cadmium, lead, hexavalent chromium, PBB, and PBDE flame retardants:

The raw materials used in the manufacturing of Eklind products have been no intentional additions of heavy metals or brominated-flame-retardants.

臭素化難燃剤 (BFR) 重金属

After reviewing engineering bills of material, supplier furnished MSDS statements and consulting with suppliers, Eklind Tool Company has concluded that the following (6) items are not contained in our products or packaging.

Lead - (Pb)  
 Mercury – (Hg)  
 Cadmium – (Cd)  
 Hexavalent Chromium (Cr, VI)  
 Polybrominated biphenyls (PBBs)  
 Polybrominated diphenyl ethers (PBDEs)

Certified By:

*Joseph Dwyer*

Joseph Dwyer, Executive VP / Manufacturing